



**Roy F. Weston, Inc.**  
Federal Programs Division  
Suite 201  
1090 King Georges Post Road  
Edison, New Jersey 08837-3703  
908-225-6116 • Fax 908-225-7037

201909



**SUPERFUND TECHNICAL ASSESSMENT AND RESPONSE TEAM**  
**EPA CONTRACT 68-W5-0019**

October 22, 1997

Mr. Eric Wilson  
U.S. Environmental Protection Agency  
Removal Action Branch  
2890 Woodbridge Avenue  
Edison, NJ 08837

EPA CONTRACT NO: 68-W5-0019

TDD NO: 02-97-05-0009B

DOCUMENT CONTROL NO: START-02-F-01439

SUBJECT: CORNELL-DUBILIER

SOUTH PLAINFIELD, MIDDLESEX COUNTY, NEW JERSEY

Dear Mr. Wilson:

Enclosed please find a photographic log which documents the site activities during the stabilization phase of the Cornell-Dubilier site. All photographs are labeled with the date and activity.

If you have any questions, do not hesitate to call me at (732) 225-6116.

Very Truly yours,

ROY F. WESTON, INC.

Brian D. McGinn  
Project Manager

Enclosure  
cc: TDD file







• Picture No. 1

Site: - Cornell-Dubilier

Date - 07/28/97

• Taken By - M. Mahnkopf (START)

• Desc. - Decon station set up in front of

• Bldg. 4A.



WATER TRUCK

97 3 28

Picture No. 2

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Water truck for dust control.



Picture No. 3

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Taped off area along southeastern  
portion of facility, behind Bldg. 14.



87 7 28



Picture No. 4

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved along eastern  
portion of facility, behind Bldg. 14.



97 7 28

Picture No. 5

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved in front of Bldg.  
13 and water tower.



Picture No. 6

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved between Bldg. 13  
and Conrail property line.



13

81 7 28



Picture No. 7

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved along eastern side  
of Bldg. 13.



Picture No. 8

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing along  
Conrail property boundary.



Picture No. 9

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. loading cleared  
debris into dump truck along Conrail  
property boundary.

NO  
DUMPING  
ALLOWED

97 7 28



Picture No. 10

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. dumping cleared  
debris in staging area.



Picture No. 11

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. Clearing along  
Conrail property line.



Picture No. 12

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing along  
loading dock at 9C.





∴

Picture No. 13

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing along  
eastern side of Bldg. 14.



Picture No. 14

Site: - Cornell-Dubilier

Date - 07/28/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing along the  
eastern corner of the developed portion of  
the facility.



Picture No. 15

Site: - Cornell-Dubilier

Date - 07/29/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. Spreading 3/4" QP  
along Conrail property line in front of  
Bldg. 7.



97-7-29



Picture No. 16

Site: - Cornell-Dubilier

Date - 07/29/97

Taken By - M. Mahnkopf (START)

Desc. - Water truck for dust control.



97 7 29

Picture No. 17

Site: - Cornell-Dubilier

Date - 07/29/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved looking  
northwest towards the water tower.



97 7 29

Picture No. 18

Site: - Cornell-Dubilier

Date - 07/29/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved along easter  
corner of the facility in front of Bldg. 13.



37 7 30



Picture No. 19

Site: - Cornell-Dubilier

Date - 07/30/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing area  
between Bldg. 10 and the water tank.



97 7 30

Picture No. 20

Site: - Cornell-Dubilier

Date - 07/30/97

Taken By - M. Mahnkopf (START)

Desc. - Water truck spraying water for dust  
control along Bldg. 11.



97 7 30

Picture No. 21

Site: - Cornell-Dubilier

Date - 07/30/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. spreading 3/4" QP  
along Bldg. 11.



97 7 31



Picture No. 22

Site: - Cornell-Dubilier

Date - 07/31/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing area between  
Bldg. 12 and Able Metro lot..



97 731

Picture No. 23

Site: - Cornell-Dubilier

Date - 07/31/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. spreading 3/4" QP  
around wooded island.



37 7 31

Picture No. 24

Site: - Cornell-Dubilier

Date - 07/31/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. spreading 3/4" QP  
behind Bldgs. 11 and 12.





Picture No. 25

Site: - Cornell-Dubilier

Date - 07/31/97

Taken By - M. Mahnkopf (START)

Desc. - Stockpiled material generated from  
clearing operations.



Picture No. 26

Site: - Cornell-Dubilier

Date - 08/01/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved between Bldg. 12  
and Able Metro lot.



Picture No. 27

Site: - Cornell-Dubilier

Date - 08/01/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. Clearing along main  
entrance driveway.



37 8 1

Picture No. 28

Site: - Cornell-Dubilier

Date - 08/01/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. clearing area in front  
of Bldg. 5.





Picture No. 29

Site: - Cornell-Dubilier

Date - 08/01/97

Taken By - M. Mahnkopf (START)

Desc. - Area to be paved along main entrance  
driveway.



Picture No. 30

Site: - Cornell-Dubilier

Date - 08/01/97

Taken By - M. Mahnkopf (START)

Desc. - Truck tire wash station set up at the  
end of the main entrance driveway.



Picture No. 31

Site: - Cornell-Dubilier

Date - 08/02/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. hand raking 3/4" QP  
along Conrail property line.







Picture No. 32

Site: - Cornell-Dubilier

Date - 08/02/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. compacting 3/4" QP at  
Bldg. 14.



91 8 2

Picture No. 33

Site: - Cornell-Dubilier

Date - 08/02/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. spreading 3/4" QP  
along Bldg. 13.



97 8 2

Picture No. 34

Site: - Cornell-Dubilier

Date - 08/02/97

Taken By - M. Mahnkopf (START)

Desc. - Bellamy Bros. checking elevations at

Bldg. 14.



Picture No. 35

Site: - Cornell-Dubilier

Date - 08/04/97

Taken By - M. Mahnkopf (START)

Desc. - Colucci Paving paving in front of  
Bldg. 7 and alongside Bldg. 8.





Picture No. 36

Site: - Cornell-Dubilier

Date - 08/04/97

Taken By - M. Mahnkopf (START)

Desc. - Colucci Paving paving in front of  
Bldg. 8.



Picture No. 37

Site: - Cornell-Dubilier

Date - 08/04/97

Taken By - M. Mahnkopf (START)

Desc. - Colucci Paving paving at Bldgs. 14  
and 15.



Picture No. 38

Site: - Cornell-Dubilier

Date - 08/04/97

Taken By - M. Mahnkopf (START)

Desc. - Tandem dump trucks delivering hot  
asphalt.





Picture No. 39

Site: Cornell-Dubilier

Date: 08/05/97

Bldg. 12 sump pump drainage pipe  
installation.



97 8 5

Picture No. 40

Site: Cornell-Dubilier

Date: 08/05/97

Bldg. 12 sump pump drainage pipe  
installation.



Picture No. 41

Site: Cornell-Dubilier

Date: 08/05/97

Colucci Paving paving next Bldg. 14 and  
behind oil tank.







Picture No. 42

Site: Cornell-Dubilier

Date: 08/05/97

Debris pile in staging area covered with poly.

(See picture no. 10)



97 8 5

Picture No. 43

Site: Cornell-Dubilier

Date: 08/05/97

Colucci Paving paving in front of oil tank and  
behind Bldg. 10.



97 8 5

Picture No. 44

Site: Cornell-Dubilier

Date: 08/05/97

PSE&G raising gas valve access cover to the  
higher new grade.



Picture No. 45

Site: Cornell-Dubilier

Date: 08/05/97

Colucci Paving paving alleyway between  
Bldg. 4A and 5A.





97 8 5

Picture No. 46

Site: Cornell-Dubilier

Date: 08/05/97

Final asphalt grade of alleyway between Bldg.  
4A and 5A.



Picture No. 47

Site: Cornell-Dubilier

Date: 08/05/97

Paved area between Bldg. 11, 10 and oil tank,  
looking towards NE side of site.



Picture No. 48

Site: Cornell-Dubilier

Date: 08/05/97

Colucci Paving paving next to Bldg. 12.







Picture No. 49

Site: Cornell-Dubilier

Date: 08/06/97

Final asphalt grade of alleyway between Bldg.  
4A and 2A.



G.A. Delivery Service, Inc.  
718 832-3910

97 8 6

Picture No. 50

Site: Cornell-Dubilier

Date: 08/06/97

Tandem dump trucks delivering hot asphalt.



97 8 6

Picture No. 51

Site: Cornell-Dubilier

Date: 08/06/97

Paved area behind Bldg. 5/5A and in front of  
Bldg. 11 and 12.



97 8 6

Picture No. 52

Site: Cornell-Dubilier

Date: 08/06/97

Colucci Paving paving next to Bldg. 12.





97 8 6

Picture No. 53

Site: Cornell-Dubilier

Date: 08/06/97

Paved parking area next to Bldg. 5 and main entrance.



Picture No. 54

Site: Cornell-Dubilier

Date: 08/07/97

Rolling asphalt in alley way between Bldg. 16  
and 9A.



97 8 7

Picture No. 55

Site: Cornell-Dubilier

Date: 08/07/97

Bellamy Bros. paving in front of Bldg. 16.







Picture No. 56

Site: Cornell-Dubilier

Date: 08/08/97

Trench for sump pump and french drain under  
loading dock next to Bldg. 12.



97 8 8

Picture No. 57

Site: Cornell-Dubilier

Date: 08/08/97

Bldg. 12 sump pump at final grade.



Picture No. 58

Site: Cornell-Dubilier

Date: 08/08/97

Bellamy Bros. paving loading docks behind  
Bldg. 5/5A.



Picture No. 59

Site: Cornell-Dubilier

Date: 08/19/97

Final grade for drainage grate in alleyway  
between Bldg. 4A and 5/5A.





97 8 19

Picture No. 60

Site: Cornell-Dubilier

Date: 08/19/97

Final asphalt grade around oil tank.



Picture No. 61

Site: Cornell-Dubilier

Date: 08/19/97

Bellamy Bros. clearing underbrush for  
perimeter fence along Spicer Ave.



**RICCARDI**  
TREE SERVICE

800 704 5706 ALPHARETTA, GA

Picture No. 62

Site: Cornell-Dubilier

Date: 08/20/97

Riccardi Tree Service trucks parked on site  
property (left of marker) along Spicer Ave.







Picture No. 63

Site: Cornell-Dubilier

Date: 08/26/97

Clearing of perimeter fence along Spicer Ave.



Picture No. 64

Site: Cornell-Dubilier

Date: 08/26/97

First posts installed for perimeter fence along  
Conrail/Bound Brook side of site.



Picture No. 65

Site: Cornell-Dubilier

Date: 08/27/97

Anchor Fence installing perimeter fence posts  
along Bound Brook side of site.



97 8 28



Picture No. 66

Site: Cornell-Dubilier

Date: 08/28/97

Fence posts installed for perimeter fence  
along Conrail/Bound Brook side of site.



Picture No. 67

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum that was damaged during  
clearing for silt fence along toe of slope.



Picture No. 68

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum that was damaged during  
clearing for silt fence along toe of slope.





Picture No. 69

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum that was damaged during  
clearing for silt fence along toe of slope.





Picture No. 70

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum that was damaged during  
clearing for silt fence along toe of slope.



Picture No. 71

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum's contents which spilled when  
drum was damaged during clearing operation.





Picture No. 72

Site: Cornell-Dubilier

Date: 08/29/97

Rusted drum that was damaged during  
clearing for silt fence along toe of slope.





Picture No. 73

Site: Cornell-Dubilier

Date: 08/29/97

Second rusted drum along toe of slope.



Picture No. 74

Site: Cornell-Dubilier

Date: 09/04/97

Fence post anchors.





97 9 5

Picture No. 75

Site: Cornell-Dubilier

Date: 09/05/97

Salvage & two drums used to contain both  
drums from spill at toe of slope.





Picture No. 76

Site: Cornell-Dubilier

Date: 09/05/97

Area under damaged drum after clean up.



Picture No. 77

Site: Cornell-Dubilier

Date: 09/05/97

Area under second drum after clean up.





Picture No. 78

Site: Cornell-Dubilier

Date: 09/05/97

Fence line along Factory Street.





Picture No. 79

Site: Cornell-Dubilier

Date: 09/09/97

Able Metro parking lot before clearing and  
prep'ing for paving.



21 8 3

Picture No. 80

Site: Cornell-Dubilier

Date: 09/09/97

Able Metro parking lot before clearing and  
prep'ing for paving.



Picture No. 81

Site: Cornell-Dubilier

Date: 09/09/97

Able Metro parking lot before clearing and  
prep'ing for paving.





Picture No. 82

Site: Cornell-Dubilier

Date: 09/09/97

Debris pile from Able Metro parking lot  
clearing and prep'ing for paving.

Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997



57 3 9

Picture No. 83

Site: Cornell-Dubilier

Date: 09/09/97

Able Metro parking lot during clearing and  
prep'ing for paving.

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997



97 9 9

**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**

**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**

Picture No. 84

Site: Cornell-Dubilier

Date: 09/09/97

Able Metro parking lot during clearing and  
prep'ing for paving.





97 9 12

**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**

Picture No. 85

Site: Cornell-Dubilier

Date: 09/12/97

Debris pile from clearing operation in  
alleyway between Bldg. 13 and 16.

**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**



Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 86

Site: Cornell-Dubilier

Date: 09/12/97

Topsoil pile to be spread in alleyway between  
Bldg. 13 and 16.



Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 87

Site: Cornell-Dubilier

Date: 09/12/97

Bellamy Bros. clearing area next to Bldg. 10  
before laying topsoil.





Picture No. 88

Site: Cornell-Dubilier

Date: 09/12/97

Debris pile from Bldg. 13 and 16 alleyway in  
staging area.

Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997



Picture No. 89

Site: Cornell-Dubilier

Date: 09/12/97

Cleared and topsoil spread in alleyway  
between Bldg. 4A & 5A.

Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997





**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

Picture No. 90

Site: Cornell-Dubilier

Date: 09/12/97

Overpack drums containing spilled drum at  
toe of slope after a rain.

**Kodak**





97 9 19

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 91

Site: Cornell-Dubilier

Date: 09/15/97

Colucci Paving paving Able Metro parking  
lot.

Kodak  
PREMIUM  
Processing  
1997



97 9 15

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

Picture No. 92  
Site: Cornell-Dubilier  
Date: 09/15/97  
Paved Able Metro parking lot.



97 9 15

Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 93

Site: Cornell-Dubilier

Date: 09/15/97

Paved Able Metro parking lot.





Picture No. 94

Site: Cornell-Dubilier

Date: 09/15/97

Paved Able Metro parking lot.

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997



97 9 16

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 96

Site: Cornell-Dubilier

Date: 09/16/97

Snow fence around woodlot.

Kodak  
TM  
ng  
17



97 9 16

**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**

Picture No. 97

Site: Cornell-Dubilier

Date: 09/16/97

Snow fence around area next to Bldg. 10.

**Kodak**





**Kodak**  
**PREMIUM**  
**Processing**  
**SEP. 1997**

Picture No. 98

Site: Cornell-Dubilier

Date: 09/17/97

Perimeter chain link fence along Spicer Ave.

**Kodak**  
**PREMIUM**  
**Processing**  
**1997**



**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

**Kodak**  
**PREMIUM**  
**Processing**  
SEP. 1997

Picture No. 99

Site: Cornell-Dubilier

Date: 09/16/97

Perimeter chain link fence along Spicer Ave.





Kodak  
PREMIUM  
Processing  
SEP. 1997

Kodak  
PREMIUM  
Processing  
SEP. 1997

Picture No. 100

Site: Cornell-Dubilier

Date: 09/16/97

Perimeter chain link fence along Spicer Ave.





Picture No. 101

Site: Cornell-Dubilier

Date: 09/18/97

Drums that were disturbed during the clearing  
of the parking lot used by Able Metro.



Picture No. 102

Site: Cornell-Dubilier

Date: 09/19/97

Bellamy Bros. digs trench for silt fence next  
to Bound Brook.





Picture No. 103

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point OT01-001, end of rip-  
rap next to formerly Pepes Driving school.





Picture No. 104

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample points DD01-001 (front) and  
ST01-001 (back).



Picture No. 105

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point DD01-002, left of silt  
fence.





Picture No. 106

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point DD01-003, left of silt  
fence.





Picture No. 107

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point PD01-001, left of silt  
fence.



Picture No. 108

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point OT01-003, center of  
picture.





97 9 23

Picture No. 109

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point ST01-002, left of  
culvert.





Picture No. 110

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point ST01-004, left of stack.



Picture No. 111

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point ST01-003, edge of  
stream, just above stack.





Picture No. 112

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point BG01-001, edge of  
stream, center of picture.





Picture No. 113

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point BG01-002, edge of  
stream, lower left of picture.



Picture No. 114

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point ST01-003, edge of  
stream, center of picture.





Picture No. 115

Site: Cornell-Dubilier

Date: 09/23/97

Environ sample point ST01-003, edge of  
stream, center of picture.





Picture No. 116

Site: Cornell-Dubilier

Date: 09/24/97

Perimeter chain link fence along Spicer Ave.  
with waring sign attached.



Picture No. 117

Site: Cornell-Dubilier

Date: 09/25/97

Warning sign placed inside snow fence in  
alleyway between Bldg. 13 & 16.





Picture No. 118

Site: Cornell-Dubilier

Date: 09/26/97

Asphalt curb which was installed by Bellamy Bros. next to Conrail tracks.





Picture No. 120

Site: Cornell-Dubilier

Date: 09/25/97

Asphalt curb which was installed by Bellamy  
Bros. next to Conrail tracks.



Picture No. 119

Site: Cornell-Dubilier

Date: 09/25/97

Asphalt curb which was installed by Bellamy  
Bros. next to Conrail tracks.





97 9 25

Picture No. 121

Site: Cornell-Dubilier

Date: 09/26/97

Outlet structure which was installed by  
Bellamy Bros. next to Conrail tracks.





Picture No. 122

Site: Cornell-Dubilier

Date: 09/26/97

Grass seed covered by hay along perimeter  
and silt fences next to Bround Brook.



Picture No. 123

Site: Cornell-Dubilier

Date: 09/26/97

Staged 55 gal. and overpack drums in a fence  
enclosed site area.





Picture No. 124

Site: Cornell-Dubilier

Date: 09/27/97

Discolored soil on top of slope, east side of  
site, covered with poly and 6" of topsoil.





Picture No. 125

Site: Cornell-Dubilier

Date: 09/27/9

Grass seed and hay covering toe of slope  
where drum spill occurred.



Picture No. 126

Site: Cornell-Dubilier

Date: 09/27/97

Discolored soil on top of slope, east side of  
site, covered with grass seed and hay.



Picture No. 127

Site: Cornell-Dubilier

Date: 09/27/97

Area around silt fence on brook side of site,  
North side, covered with grass seed and hay.





Picture No. 128

Site: Cornell-Dubilier

Date: 09/27/97

Outlet structure, north side of site.



Picture No. 129

Site: Cornell-Dubilier

Date: 09/27/97

Second outlet structure, north side of site.





Picture No. 130

Site: Cornell-Dubilier

Date: 09/29/97

End of perimeter fence, next Bldg. 7 and  
along Conrail RR tracks.





97 9 30

Picture No. 131

Site: Cornell-Dubilier

Date: 09/30/97

Perimeter fence completed inclosing unpaved  
east area of site.



Picture No. 132

Site: Cornell-Dubilier

Date: 10/01/97

Perimeter fence completed inclosing unpaved  
east area of site.



Picture No. 133

Site: Cornell-Dubilier

Date: 10/01/97

Wood snow fence closing off alleyway behind  
Bldg. 7.





97 10 1

Picture No. 134

Site: Cornell-Dubilier

Date: 10/01/97

Chain link fencing enclosing area formally  
used by New Brunswick Roofing.



Picture No. 135

Site: Cornell-Dubilier

Date: 10/01/97

Chain link fencing enclosing area formally  
used by New Brunswick Roofing.